



Machining area (X-Y-Z)

Machining area X

mm

from 10000 to 50000

Machining area Y

mm

3200 ÷ 4500

Work piece passage Z

mm

360